



TDA 1060 = NE5560 = B260 D
 LM224N = TDE0124 DP
 PD-80 Replacement: GBU606

Common faults: 78M12, TDE0124 DP