



TDA 1060 = NE5560 = B260 D  
 LM224N = TDE0124 DP  
 2KPBD8 Replacement: GBU606

Common faults: 78M12, TDA1060